

Power Climber®

PURPOSE

PCEU 25-004 Rev B Premature Gear Wear on P2514/P2314 Hoists

July 18, 2025

outlines required inspection procedures and corrective actions to maintain safe operation and prevent potential in-service failures.				
COMPLIANCE CATEGORY Safety Failure to comply with this product update could result in personal injury and/or death. Compliance is mandated within a specific operating time. Compliance Required Identifies the need for action to correct a condition that, if left uncorrected, may result in reduced equipment reliability or efficiency. Compliance may be required within a specific operating time.	PRIORITY CODE ☐ 1 Prior to unit startup or prior to continued operation (Immediate Action Required) ☐ 2 At first opportunity (Prior to Next Scheduled Maintenance Interval)			
☐ Optional Identifies changes that may be beneficial to some, but not necessarily all. Accomplishment at customers discretion.	☐ 3 Next Scheduled Maintenance Interval			
Customer communication, no action required.	Optional / Notification			
PRODUCT MODELS AFFECTED P2514/P2314				
F2314/F2314				
COMPONENT SYSTEM Electrical Mechanical	Safety Other:			
SUB COMPONENT				
Ring Gear and Pinion Gears				
ACTION REQUIRED				
 Effective Immediately: All P2514 and P2314 hoists must be inspected by a certified technician at a qualified Power Climber or BrandSafway service location for signs of premature ring gear wear. If the hoist is not currently in use: It should be inspected immediately before being returned to service. If the hoist is currently in use and has accumulated more than 30 hours of operation: It must be removed from service and inspected at the next available opportunity. Daily before each use: Verification if hoist has exceeded 30 hours of use and if so, it must be removed from service and inspected at the next available opportunity. If unusual noise is heard from within the hoist, stop use and remove unit from service and inspect at the next available opportunity. 				
Inspection Requirements:				
 Immediate review of the ring gear for signs of wear: Uneven or excessive wear on gear teeth 				
Chipped, pitted, or deformed gear teeth Chipped, pitted, or deformed gear teeth				

Continued next page $\rightarrow \rightarrow \rightarrow \rightarrow \rightarrow \rightarrow \rightarrow \rightarrow$

Missing gear teeth

Discoloration or scoring indicative of abnormal contact

Unusual noise or vibration during operation Inadequate amount of grease applied





Product Update

PCEU 25-004 Rev B

Premature Gear Wear on P2514/P2314 Hoists

July 18, 2025

Power Climber®

Post-Inspection Actions:

- If no wear is found:
 - Reapply grease to all ring gear teeth as outlined in P2514/P2314 Service Instructions before reassembly.
- If wear is identified:
 - Both pinions and the ring gear must be replaced per the Service Instructions.
- A completed checklist as per attached must be submitted for each hoist inspected to ProductSupport@SpiderStaging.com

Ongoing Preventive Maintenance:

- O Until further notice, all affected hoists must be inspected:
 - After each rental
 - During annual maintenance

This enhanced inspection frequency is required while Engineering continues to assess long-term field performance and wear patterns.

• IMPORTANT – Overspeed Safety Lock (OSL) Protocol:

- If the OSL has engaged, do not reset the unit.
- Immediately notify your supervisor
- o Apply Lockout/Tagout (LOTO) procedures
- o The OSL must be inspected by a qualified service location to determine whether further damage occurred due to an impact event.

ACCOMPANYING DOCUMENTS





Checklist for P2514/P2413 inspections (see PCEU 25-004 Rev B.)

1	Company Name and Location:	
2	Date of Inspection:	
3	Name of person performing the inspection:	
4	What is the Serial Number on the Nameplate of the hoist? What is the Serial Number stamped into the housing?	Nameplate SN:
	Spider by Francishery Spider by Francishery 305 Upland Drive, Scottle, WA 98.88 USA BY BIRANG SIAPHAY. 877-774-3370 www.spidentaging.com Serial-No. Numero de Serie B 2 0 1 9 7 7 8	Housing SN:
	NAMEPLATE HOUSING (may vary by model)	: - -
5	What is the Serial Number inside the electrical box compartment door? Compartment Compartment	
6	What is the date code on the front face of the existing ring gear (could be etched or written – if written, please provide photo)?	
7	Upon inspection of the ring gear (per service manual, remove wear blocks and lift highlighted seal to inspect), was any wear found?	○ Yes ○ No

Continued next page $\rightarrow \rightarrow \rightarrow \rightarrow \rightarrow \rightarrow \rightarrow \rightarrow$



If yes, what was found? (please attach photos upon return to ProductSupport@SpiderStaging.com)			
ring gear must be replaced. Confirm replacement has been completed. Pinion Part Number Americas = UP-12222.02 Ring Gear Part Number Americas = UP-12222.01-03 Rest of World = D12222.01-03 Rest of World = D12222.01-03 Rest of World = D12222.01-03 Was it reported that the OSL had an activation? Yes No 12 If you have confirmed "Yes" to question 11 or checked "Missing gear teeth" for question 8: Please record who the person is that performed the OSL inspection here:	8		 Chipped, pitted, or deformed gear teeth Missing gear teeth Discoloration or scoring indicative of abnormal contact Unusual noise or vibration during operation
 Americas = UP-12222.01-03 Rest of World = D12222.01-03 If you have confirmed "Yes" to question 9, what is the date code on the front face of the NEW ring gear you installed? Was it reported that the OSL had an activation? No If you have confirmed "Yes" to question 11 or checked "Missing gear teeth" for question 8: 	9	ring gear must be replaced. Confirm replacement has been completed. • Pinion Part Number • Americas = UP-12222.02	
code on the front face of the NEW ring gear you installed? 11 Was it reported that the OSL had an activation? No 12 If you have confirmed "Yes" to question 11 or checked "Missing gear teeth" for question 8: Please record who the person is that performed the OSL inspection here:		o Americas = UP-12222.01-03	
No 12 If you have confirmed "Yes" to question 11 or checked "Missing gear teeth" for question 8: Please record who the person is that performed the OSL inspection here:	10		
"Missing gear teeth" for question 8: here:	11	Was it reported that the OSL had an activation?	
	12	"Missing gear teeth" for question 8:	·