

PURPOSE

An upgrade to the electromagnetic brake on older PC1 hoists is now available. The upgrade will prevent the brake from operating incorrectly in adverse climates and/or operating conditions should the brake not have been inspected/serviced properly. This upgrade is included on all hoists manufactured since January 2009. If your hoist was manufactured prior to this date, we recommend that you implement this upgrade.

Please note that the release of this upgrade is not a substitute for proper service. Always follow the manufacturers recommendations for service. An improperly serviced or damaged primary brake can pose serious risks to your personal safety and/or damage property.

<p>COMPLIANCE CATEGORY</p> <p><input type="checkbox"/> Safety Failure to comply with this product update could result in personal injury and/or death. Compliance is mandated within a specific operating time.</p> <p><input type="checkbox"/> Compliance Required Identifies the need for action to correct a condition that, if left uncorrected, may result in reduced equipment reliability or efficiency. Compliance may be required within a specific operating time.</p> <p><input checked="" type="checkbox"/> Optional Identifies changes that may be beneficial to some, but not necessarily to all. Accomplishment at customers discretion.</p> <p><input type="checkbox"/> Notification Customer communication</p>	<p>PRIORITY CODE</p> <p><input type="checkbox"/> 1 Prior to unit startup or prior to continued operation (Immediate Action Required)</p> <p><input type="checkbox"/> 2 At first opportunity (Prior to Next Scheduled Maintenance Interval)</p> <p><input type="checkbox"/> 3 Next Scheduled Maintenance Interval</p> <p><input checked="" type="checkbox"/> 4 Notification</p>
--	--

PRODUCT MODELS AFFECTED

PC1

COMPONENT SYSTEM

Electrical Mechanical Safety Other:

ACTION REQUIRED

Power Climber strongly recommends that if your hoist was manufactured prior to 2009 that you purchase an upgrade that will prevent the electromagnetic brake from operating incorrectly in adverse climates and/or operating conditions (should the unit not have been serviced appropriately), please reach out to Power Climber via the contact information below.

The part number for the upgrade is 722448-1 (Brake Kit;15 NM Upgrade/Rebuild) and an illustration of the included components are shown on the following page. For service instructions please refer to the service manual for the appropriate hoist you are working with. If you do not have a service manual, please reach out to Product Support via the contact information below.

